

Responsible: N. Kirchmair
Date: 11.10.2006

Telephone: (0209) 401 718
Fax: (0209) 401 743



Honeycomb pan detection

EKWE 320 W/S

When the pan detection device malfunctions the cause of the fault is frequently the pan detection connection cable from the control honeycomb to the heating honeycomb.

The crimping of the AMP plug on the heating zone is to be checked or re-pressed. In future these connections will no longer be pressed; they will be welded instead.