
GH506.0 / GH606.0 / GKH 507.0**Ignition problems with the electric spark ignition on upright gas appliances '97**

From January 1999, upright gas appliances will be fitted with new transformers.

These transformers are supplied with a higher ignition voltage and a faster clock speed.

This will eliminate all ignition problems.

The following ignition transformers are available now under these Spare-part numbers:

GH 506.0	Spare-part no.	53 67 70
GH 606.0	Spare-part no.	53 67 68
GKH 507.0	Spare-part no.	53 67 69

The following points must be noted when fitting:

The accompanying earthing cable must be attached to the ignition transformer's earthing terminal with a 6.3 mm AMP-plug and then screwed tight with the ring eye under the transformer's fixing screw.