

Responsible: U. Laarmann
Date: 30.01.2006

Tel.: (0209) 401 732
Fax: (0209) 401 743



IKD1157.1 E and KD957.1 E - Factory 77 **Grease drips from the motor into the rear halogen lamp**

In unfavourable operational conditions it may occur that grease from the fan motor drips and then gets into the rear halogen lamp, damaging it.

For cases in which the exhaust air duct has no fault or if it is no longer possible to modify the exhaust air duct we have developed a plastic cover (spare-part no. 531428).

This cover is mounted onto the rear halogen lamp.

1. Remove the halogen lamp.
2. Put on the plastic cover.
3. Replace the halogen lamp

Fig. 1 Plastic cover



Fig. 2 Remove the halogen lamp



Fig. 3 After installation

