

Responsible: U. Laarmann
Date: 07.03.2007

Tel.: (0209) 401 732
Fax: (0209) 401 743



EDIP 939.1 E and EDIP 639.1 E Replacement of halogen lamp is not possible

As described in the Operating Manual, replacement of the halogen lamps of the above-mentioned devices is impossible for the customer.

The reason is a wrong design of the metal plate. This metal plate must be replaced by another metal plate with the respective spare part numbers:

EDIP 639.1E 531886

EDIP 939.1E 531887

