

Responsible: D. Rutz
Date: 27.07.2004

Tel: (0209) 401 733
Fax: (0209) 401 743



**Modified sumpcover (rotor hub for the lower spray arm)
IGV 645.0 / .1 / .2**

Problems with spray arms which are touching the feed tube. Modification introduced in production since week 10/'04. Spare part number still the same: 434 773. Old parts were scrapped.

Note: the snap-in locking for the feed tube is a one-time connection. To avoid any damages, install the system (cover, cover sieve and feed tube) outside the appliance. The reason is, it is easier to control, if the connection is correct. Don't check the connection too hard after installation to avoid a release.

Modified cover



"Old" cover



Actual Version since 08.09.2003:

