


Responsible: Dieter Rutz
Date: 28.05.2010

Tel.: (0209) 401 733
Fax: (0209) 401 743



New slot on the connection (pos. 1) of the module control spare-part no. 436 022

The slot on the right is no longer four-fold; it is now only a double connection.



If the plug no longer fits into position 1 (on the right), it is to be inserted into position 2.

