Support

Responsible: Dieter Rutz Date: 14.08.2014 Tel.: (0209) 401 733 Fax: (0209) 401 743

Drain pump blockages

Description

It is possible for drain pumps from manufacturer Leili produced before 24.05.2013 to become jammed.

Solution

1. Identify the drain pump you have by comparing the data label with those below. The later pumps also have a support bracket.



2. Replace with a new one produced after 24.05.2013. Do not unblock the pump, replace with a new one! Specific part numbers can be located on TDS for the model you have.

Models involved

All PNCs.

