

Problems with replacing the fridge-freezer thermostats – factory no. 80

On replacing the thermostats, namely *RANCO instead of ATEA* or *ATEA instead of RANCO*, the terminal block on the thermostat needs to be turned by 90°.

To do so, the AMP connectors need to be detached and then put back into position again once the terminal block has been turned. Identification marking is on the terminal block, namely R for RANCO and A for ATEA

Illustration 1. Atea thermostat



Illustration 2. Ranco thermostat

