

Tempi di passo (in sec.)		Funzioni		Incrementi		Partenze Progr.	
1	30	S C	L res	1	30	1	30
2	30	S C	L res	2	30	2	30
3	30	S C	L res	3	30	3	30
4	30	S C	L res	4	30	4	30
5	30	S C	L res	5	30	5	30
6	30	S C	L res	6	30	6	30
7	30	S C	L res	7	30	7	30
8	30	S C	L res	8	30	8	30
9	30	S C	L res	9	30	9	30
10	30	S C	L res	10	30	10	30
11	30	S C	L res	11	30	11	30
12	30	S C	L res	12	30	12	30
13	30	S C	L res	13	30	13	30
14	30	S C	L res	14	30	14	30
15	30	S C	L res	15	30	15	30
16	30	S C	L res	16	30	16	30
17	30	S C	L res	17	30	17	30
18	30	S C	L res	18	30	18	30
19	30	S C	L res	19	30	19	30
20	30	S C	L res	20	30	20	30
21	30	S C	L res	21	30	21	30
22	30	S C	L res	22	30	22	30
23	30	S C	L res	23	30	23	30
24	30	S C	L res	24	30	24	30
25	30	S C	L res	25	30	25	30
26	30	S C	L res	26	30	26	30
27	30	S C	L res	27	30	27	30
28	30	S C	L res	28	30	28	30
29	30	S C	L res	29	30	29	30
30	30	S C	L res	30	30	30	30
31	30	S C	L res	31	30	31	30
32	30	S C	L res	32	30	32	30
33	30	S C	L res	33	30	33	30
34	30	S C	L res	34	30	34	30
35	30	S C	L res	35	30	35	30
36	30	S C	L res	36	30	36	30
37	30	S C	L res	37	30	37	30
38	30	S C	L res	38	30	38	30
39	30	S C	L res	39	30	39	30
40	30	S C	L res	40	30	40	30
41	30	S C	L res	41	30	41	30
42	30	S C	L res	42	30	42	30
43	30	S C	L res	43	30	43	30
44	30	S C	L res	44	30	44	30
45	30	S C	L res	45	30	45	30
46	30	S C	L res	46	30	46	30
47	30	S C	L res	47	30	47	30
48	30	S C	L res	48	30	48	30
49	30	S C	L res	49	30	49	30
50	30	S C	L res	50	30	50	30
51	30	S C	L res	51	30	51	30
52	30	S C	L res	52	30	52	30
53	30	S C	L res	53	30	53	30
54	30	S C	L res	54	30	54	30
55	30	S C	L res	55	30	55	30
56	30	S C	L res	56	30	56	30
57	30	S C	L res	57	30	57	30
58	30	S C	L res	58	30	58	30

152 681401b.IT

LEGENDA Funzioni

S = Scarico / C = Carico / L = Lavaggio / R = Riscaldamento /

$P = \text{Attesa pressostato sul pieno } (1/3) / P < = \text{Attesa pressostato sul vuoto } (1/2) / T = \text{Attesa temperatura} /$

Deter = Detersivo / Brill = Brillantante / Rigen = Rigenera / L_res = Lavaggio resine /