

Bearbeitung/ *Responsible*: Dieter Rutz
Datum / *Date*: 27.08.2014

Telefon: +49 (0)209 401-733
Fax: +49 (0)209 401-743

Nach gewählter Zeitvorwahl startet das Gerät am Programmende erneut

Wird nach aktivierter Zeitvorwahl am Programmende die Tür geöffnet und wieder geschlossen, kann das Gerät selbsttätig den nächsten Programmablauf starten.

Grund: Fehlerhafte Software im Bedienmodul
Betroffene Geräte: IGV 6508.1 / IGV 6509.2 / IGV 6509.1
IGV 6509.3 / IGVS 6509.1 / IGVS 6509.2
IGVE 6610.0 / IGVS 6509.3
Betroffen sind nur Geräte mit folgenden
Materialnummern des Bedienmoduls, die ab FD 9106 bis einschließlich
FD 9308 gefertigt wurden.
Bedienmodule: 437016 und Erstes Modul 437849
Abhilfe: Austausch folgender Bauteile:

Original Modul	Ersatz Modul
437016	437849

The appliance will restart at the end of program after a wash with chosen delay timer

If the door is opened and closed after a wash where the delayed timer was used, the appliance can possibly restart a new wash on its own.

*Reason: Error in the control module software.
Models affected: IGV 6508.1 / IGV 6509.2 / IGV 6509.1
IGV 6509.3 / IGVS 6509.1 / IGVS 6509.2
IGVE 6610.0 / IGVS 6509.3
Only the appliances with the following control modules, built from FD 9106 until FD 9308, are affected.
Error code: 437016 and first modul 437849
Solution: Replacement of the following components:*

<i>Original Module</i>	<i>Replacement Module</i>
437016	437849