

Responsible: D. Rutz
Date: 07.03.2007

Tel.: (0209) 401 733
Fax: (0209) 401 743



Thermal behaviour in the warming drawer of the WS 6015.OE

Turning the thermostat control enables temperatures of between 30°C and 80°C to be selected. The temperature scale is not marked in absolute temperatures in °C; it is marked with three symbols which stand for the following settings:

- Minimum temperature 40° C
- Medium temperature 60° C
- Maximum temperature 80° C.

The diagram below shows the temperature behaviour in an empty warming drawer at a maximum temperature setting (80°C). The temperature shown in the diagram is an average temperature taken from four measuring points in the warming drawer. Temperatures set will have been regulated after approx. 35 minutes.

