

Responsible: D. Rutz
 Date: 20.04.2001

Tel.: (0209) 401 732
 Fax: (0209) 401 743



New electronic with new key-technology

The following glass ceramic hobs will receive new electronic:

	old spare-parts no.	new spare-parts no.	
EKE 854.1	164832	164873	1 to 1 exchange
KC 960.30	164832	164873	1 to 1 exchange
EKE 604.1	-----	539425	
EKE 604.2	164821	539425	
EKE 804.2	164836	539425	

When installing the new electronic the DIP-switches must be changed according to the diagram. (It is not necessary any more to use the laptop for this)

Remaining stock of the old electronic must be used.
 However, it must not be built into variance -66 (Thielmann production).

