

Responsible: D. Rutz  
Date: 30.05.2007

Tel.: (0209) 401 733  
Fax: (0209) 401 743



### **200 mA micro-fuse defect**

If the 200mA micro-fuse (**spare-part no. 537 480**) of the electronic system of the EEH / EEB cook centres and the glass ceramic hobs develops a fault for no apparent reason, it is to be replaced with a micro-fuse 1 (**spare-part no. 509 542**).