

## EEB 6800.5

### Moisture behind the glass panel

#### Problems with operating the electronic unit due to moisture

### Two-step remedy

#### Step 1 - Sealing

1. Remove the appliance.
2. Disconnect the appliance from the mains.
3. Screw off the two screws of the cover behind the control panel and remove the cover.
4. Screw off the four screws of the back wall of the appliance and remove it.
5. Screw off the four screws of the cover with the cross-flow fan duct and remove the cover.
6. Turn the bottom of the cover upwards and apply the sealant (spare-part no. 535565) to the front edge across the full width of the appliance.
7. Re-mount the cover with the cross-flow fan duct. The seal is now located between the control panel support and the cover.
8. Replace the cover behind the control panel.
9. Carry out a VDE 0701 test and reinstall the appliance.



#### Step 2 - Sealing

1. Remove the oven door.
2. Seal the gap between the glass switch panel and the control panel holder from beneath across the full width of the panel with Pactan (spare-part no. 091580).

