

Responsible: Dieter Rutz
Date: 28.05.2010

Tel.: (0209) 401 733
Fax: (0209) 401 743



EEBD 6600.1E Unnecessary key in the new circuit board

The operating element bearing **spare-part no. 542 587** is supplied with seven keys! Since six keys are sufficient for the control panel of the EEBD 6600.1, the seventh key (right on the left of the switch panel, without a symbol) will need to be deactivated.



The control cam for this key must be broken off as no opening has been provided for it in the control panel and the control cam, depending on the pressure exerted on the other keys, will immediately trigger an error.

