

Responsible: U. Laarmann
Date: 22.11.2005

Tel.: (0209) 401 732
Fax: (0209) 401 743



New electronic unit for KD930.0 / KD630.0

Since a bulb short-circuit has repeatedly resulted in breakdowns in the electronic unit (spare-part no. 538146) of the KD 930.0 / KD630.0 cooker hoods, an new electronic unit with a back-up fuse (delay-action 5A, dimensions (mm) 5x20, diameter x length) has been developed.

On replacement, the electronic unit bearing the spare-part no. 531307 must be installed.

Under no circumstances may the electronics unit (spare-part no. 538146) be re-installed in the appliance!

Should a short-circuit result in failure of the new electronic unit (spare-part no. 531307), only the fuse will need to be replaced in future. The spare-part no. of the 5A fuse is 531357.