

Charcoal filter

**KD6250 / KD9250 / KD9350.0 / KD 12350.0 / IKD 9350.0 / IKD 12350.0 / IKDEM 12350.0 /
IKDEM 9350.0 / KDEM 12350.0 / KDEM 9350**

When using the charcoal filter ZUB 612 (spare-part no. 538022) in the cooker hoods shown above, the construction form of the charcoal filter may cause problems when absorbing vapours in the recirculation air mode (see Figure 1).



Fig. 1: Installation situation with a charcoal filter model ZUB 612

The filter will need to be replaced with a new grease filter and charcoal filter (charcoal filter mat) (Figure 2).




Fig. 2: Grease filter with a charcoal filter and fastening clamp

These filters can be purchased with the following spare-part numbers:

- Spare part no. 543957 08087158 = Metal grease filter including a fastening clamp
- Spare part no. 543958 03300491 = Charcoal filter

Individual fastening clamps are not available.



Fig. 3: Installation situation after installation of the new grease filter with the charcoal filter mat