

Responsible: M. Kuehne
Date: 22.11.2005

Tel.: (0209) 401 756
Fax: (0209) 401 743



EKV6800.0 EKVW 6800.0

Concerns: Spare-part nos 527166 and 527167 - two-way solenoid valves

The components of the valves have been changed

Modification to the coil means that the old connections no longer fit.

When the electric coils are replaced (110V / 230 V) the following parts must be ordered too and then installed.

Use the cable binders supplied to tie off leads no longer required and the remaining leads.

Spare part no. 531 399

Connection of a single clamp 1/8" (1 unit)

Spare part no. 531 451

Aluminium washer 107 14 x 1.5 (2 units)

Spare part no. 531 404

Single ring 1/8"

Spare part no. 531 329

Connection piece 1/8"

Spare part no. 531 210

Hose connection 1/8"

