

**IKE 318-4-2T: plastic strip of the evaporator is warped**

Should it not be possible to push the middle drawer right in, proceed as follows:



Use a 2.5 mm steel drill to drill a hole from the bottom in the middle of the plastic strip of the evaporator (see illustrations). When drilling press the plastic strip firmly onto the evaporator.

Fasten the evaporator plastic strip with the fastening clip, **spare part no. 432417**.



Evaporator from the bottom

