



Turntable motor with 2.5/3 r.p.m.(Metallic shaft)

References involved: MC 32 BIS; MW 32 BIS; MW 32 BIT

If a fail occurs in the turntable motor verify:

- the value of the coil between the terminals should be 14.7 K Ω ;
- if the connector of the wiring has good contact.



Spare-parts n. 162030 - Turntable motor with metallic shaft

Spare-parts n. 163223 - Sealing washer for turntable motor

Spare-parts n. 163220 - Isolation Mica