

Responsible: Dieter Rutz
Date: 10.05.2013

Tel.: (0209) 401 733
Fax: (0209) 401 743



EEB 6360.0
Cross flow fan follow-up time

The follow-up time of the cross flow fan is no longer controlled with a thermostat; it depends on the time when the oven is switched on.

The times have been stored in EEprom (see chart)

Switch-on (minutes)	Follow-up time (minutes)
$5 > t < 10$	5
$10 > t < 20$	10
$20 > t < 25$	15
$25 > t < 35$	20
$35 > t < 45$	25
longer than 45	30