

Responsible: Uwe Laarmann
Date: 03.07.2008

Tel.: (0209) 401 732
Fax: (0209) 401 743



KD 9475.0 GE-91
Touch control, spare-part no. 530397

When replacing the touch control, it is essential to disconnect the hood from the mains.

The hood may only be re-connected to the mains once the touch control has been properly installed.

This is essential because the touch control calibrates itself when power is applied for the first time.

If calibration takes place before the touch control is properly installed, it will not function at all or will not function properly once it has been correctly installed.