

Responsible: D. Rutz
Date: 22.07.2004

Tel: (0209) 401 733
Fax: (0209) 401 743



Rubber outlet of the circulation pump Models:IGV 645.0 / .1 / .2

Possible leakages or noises on the circulation pump. Check the rubber outlet of the circulation pump to the sump. Now it is possible to order the circulation pump itself. It is not longer necessary to change the whole motor/pump unit. To avoid wrong orders, please have a look on the below mentioned pictures to the different motors. Take care on appliances with CESET synchronous-motors for permanent and alternating washing system. On the housing of the pump, you can find a "L" or a "H" on the end of the labelling. "L" for low pressure pump and "H" for high pressure pump.



LOW NOISE MOTOR (alternating)
Spare parts n. 435 450



ASYNCHRONOUS MOTOR (permanent)
Spare parts n. 435 451



CESET SYNCHRONOUS MOTOR
(alternating)
Spare parts n. 435 452



CESET SYNCHRONOUS MOTOR
(permanent)
Spare parts n. 435 453