

IKE 238-4-2T

Temperature in the fresh foodstuffs refrigeration compartment too low

A regulator that controls the fan and has permanent settings governs the temperature in this compartment. Setting tolerances may result under some circumstances in the temperature being too low.

Troubleshooting: The air thermostat is set to -9.5°C out and a constant 0°C in. Remove the left flap (illustration) and turn the thermostat with a screwdriver a quarter to half a turn counter-clockwise. This sets a higher temperature in this compartment.



Turn counter clockwise

Put the caps back on and carry out a function test.

Caution: In some cases the air duct (Spare part n. 430870) may be damp. If so, always replace it.